

First, press and hold the rocker switch in the extend position. Place the negative lead of the digital volt meter on the Black wire position of the pigtail and the positive lead of the volt meter on ...